STATE OF FLORIDA **DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT**



1 of 2

Facility Information

Permit Number: 13-51-2136187

Name of Facility: Andrea Castillo Prepatory Academy K-8

Address: 10201 NW 78TH Street

City, Zip: Miami 33178

Type: Public Schools

Owner: Public School, Miami Dade County - Andrea Castillo Prepatory Acad

Person In Charge: Andrea Castillo Prepatory Academy K-8 Phone: (786) 275-0464

PIC Email: acosta@dadeschools.net

Inspection Information

Purpose: Routine Begin Time: 08:30 AM Inspection Date: 8/24/2023 End Time: 09:30 AM

Additional Information

FEMALES 190 CENSUS 360 MALES 170

This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.

Violation Markings

SCHOOL SANITATION

IN 1. School Site

IN 2. Playground, Equip & Athletic Fields*

N 3. Athletic & Playground Equipment BUILDING CONST/MAINT.

IN 4. Construction

OUT 5. Maintenance & Repair

N 6. Lighting Standards

N. T. Heating, Ventilation, A/C StandardsN. Natural Ventilation

9. Mechanical Ventilation SANITARY FACILITIES

IN 10. Provided/Accessible/Separation

IN 11. Group Toilet Rooms

IN 12. Toilet Facilities

IN 13. Handwashing Facilities

IN 14. Soap Dispensers

IN 15. Shower Facilities

NA 16. Showers Water Temperatures

WATER SUPPLY

IN 17. Approved Source IN 18. Drinking Fountains

LIQUID WASTE & WASTE WATER

IN 19. Sewage Disposal

IN 20. Solid Waste

PEST CONTROL

IN 21. Pest Control

SAFFTY

IN 22. First Aid Kit

DIAPER CHANGING STATION

RESULT: Satisfactory

Correct By: Next Inspection

Re-Inspection Date: None

NA 23. Sanitizers

NA 24. Changing Station & Mats

NA 25. Hand Sink

NA 26. Garbage Can

ANIMAL HEALTH & SAFETY

NA 27. Animal Maintenance/Aggressive DORM/RESIDENTIAL FACILITIES

NA 28. Maintenance/Complaint

NA 29. Other

Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occurring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation

Violation Key: * = 2. Playground, Equipment & Athletic Fields

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-2136187 Andrea Castillo Prepatory Academy K-8

STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT



2 of 2

General Comments

Group Inspection:

Brand new school. Adolfo Costa (Principal) and Nelson Jimenez (Head Custodial), assisted with inspection.
Cristina Gil (AP).
At the time of inspection:
Shower on Campus (Clinic). Unable to measure shower water temperature (occupied by wheelchairs).
This to measure shower water temperature (occupied by whosteriality).
Email Address(es): acosta@dadeschools.net;
cctgil@dadeschools.net;
<u>Violations Comments</u>
Violation #5. Maintenance & Repair
Observations:
Stains on Ceiling Panels:
1. Room # 1108 (two (2) stained ceiling panels).
Replace two (2) stained ceiling panels.
Replace two (2) stained ceiling panels. Corrected on Site (COS).
Replace two (2) stained ceiling panels.
Replace two (2) stained ceiling panels. Corrected on Site (COS).
Replace two (2) stained ceiling panels. Corrected on Site (COS).
Replace two (2) stained ceiling panels. Corrected on Site (COS).
Replace two (2) stained ceiling panels. Corrected on Site (COS). At the time of inspection, Head Custodial replaced two (2) stained ceiling panels in Room # 1108.
Replace two (2) stained ceiling panels. Corrected on Site (COS). At the time of inspection, Head Custodial replaced two (2) stained ceiling panels in Room # 1108. CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean,
Replace two (2) stained ceiling panels. Corrected on Site (COS). At the time of inspection, Head Custodial replaced two (2) stained ceiling panels in Room # 1108.

Inspection Conducted By: Alberto Reyes (032763) Inspector Contact Number: Work: (305) 623-3500 ex.

Print Client Name: Date: 8/24/2023

Inspector Signature:

Client Signature:

Form Number: DH 4030 12/16A 13-51-2136187 Andrea Castillo Prepatory Academy K-8