

**STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT**



1 of 3

**Facility Information**

**RESULT: Satisfactory**

Permit Number: 13-51-2136187 Name of Facility: Andrea Castillo Prepatory Academy K-8 Address: 10201 NW 78TH Street City, Zip: Miami 33178  Type: Public Schools Owner: Public School, Miami Dade County - Andrea Castillo Prepatory Acad Person In Charge: Andrea Castillo Prepatory Academy K-8      Phone: (786) 275-0464 PIC Email: acosta@dadeschools.net	<p><b>Correct By: Next Inspection</b></p> <p><b>Re-Inspection Date: None</b></p>
---	--

**Inspection Information**

Purpose: Routine Inspection Date: 7/25/2024	Begin Time: 12:30 PM End Time: 01:40 PM
--	--

**Additional Information**

FEMALES ..... 178 MALES ..... 229	CENSUS ..... 407
--------------------------------------	------------------

*This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.*

**Violation Markings**

SCHOOL SANITATION <b>IN</b> 1. School Site <b>IN</b> 2. Playground, Equip & Athletic Fields* <b>IN</b> 3. Athletic & Playground Equipment BUILDING CONST/MAINT. <b>IN</b> 4. Construction <b>OUT</b> 5. Maintenance & Repair <b>IN</b> 6. Lighting Standards <b>IN</b> 7. Heating, Ventilation, A/C Standards <b>IN</b> 8. Natural Ventilation <b>IN</b> 9. Mechanical Ventilation SANITARY FACILITIES <b>IN</b> 10. Provided/Accessible/Separation	<b>IN</b> 11. Group Toilet Rooms <b>IN</b> 12. Toilet Facilities <b>IN</b> 13. Handwashing Facilities <b>IN</b> 14. Soap Dispensers <b>IN</b> 15. Shower Facilities <b>IN</b> 16. Showers Water Temperatures WATER SUPPLY <b>IN</b> 17. Approved Source <b>OUT</b> 18. Drinking Fountains LIQUID WASTE & WASTE WATER <b>IN</b> 19. Sewage Disposal <b>IN</b> 20. Solid Waste PEST CONTROL	<b>IN</b> 21. Pest Control SAFETY <b>IN</b> 22. First Aid Kit DIAPER CHANGING STATION <b>NA</b> 23. Sanitizers <b>NA</b> 24. Changing Station & Mats <b>NA</b> 25. Hand Sink <b>NA</b> 26. Garbage Can ANIMAL HEALTH & SAFETY <b>NA</b> 27. Animal Maintenance/Aggressive DORM/RESIDENTIAL FACILITIES <b>NA</b> 28. Maintenance/Complaint <b>NA</b> 29. Other
---	---	---

*Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occurring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation*

*Violation Key: \* = 2. Playground, Equipment & Athletic Fields*

Inspector Signature:

Client Signature:

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



2 of 3

**General Comments**

Group Inspection:  
Brand new school.  
Adolfo Costa (Principal).  
Odalys Paez (Head Custodial), assisted with inspection.  
Cristina Gil (AP).  
Charisse D. McKenzie (Principal s Secretary) signed the inspection.  
At the time of inspection:  
Shower on Campus (Clinic).  
Showerhead temperature 95.1°F.

Email Address(es): acosta@dadeschools.net;  
cctgil@dadeschools.net;

Inspector Signature:

Handwritten signature of the inspector, appearing to be "AL".

Client Signature:

Handwritten signature of the client, appearing to be "Chi".

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



3 of 3

**Violations Comments**

**Violation #5. Maintenance & Repair**

**Observations:**

**Detaching Tiles:**

1. Hallway by EXIT Doors (detaching tiles from floor base).

Repair detaching doors from base.

2. Room # 1137 (detaching tiles from floor base)

Repair detaching tiles from floor base.

3. Room # 1143 (detaching tiles from floor base).

Repair detaching tiles from floor base.

**Hole in the Wall:**

1. Room # 1128 (one (1) hole on the wall above the electrical outlet).

Repair hole in the wall by Room # 1128.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

**Violation #18. Drinking Fountains**

**Observations:**

**Water Fountain Out-of-Service:**

1. Room # 1137 (one (1) water fountain out-of-service).

Provide water flow in water fountain.

CODE REFERENCE: 18. Drinking Fountains. 5(16)(b)9 SREF. Drinking fountains shall be maintained in an operational condition at all times. 5(1)(e)8.b SREF. Toilet rooms, shower and locker rooms, drinking water fountains, and clinics shall be cleaned & disinfected daily using an appropriate Germicidal Detergent. Note: Drinking fountains shall be rinsed or flushed with plain water after disinfection. 468.3.5.1 FBC. Educational & ancillary facilities shall have drinking fountains for all occupants, in ratios & accessible as required.

Inspection Conducted By: Alberto Reyes (032763)  
Inspector Contact Number: Work: (305) 623-3500 ex.  
Print Client Name: Charisse D. McKenzie (Principal s Secretary).  
Date: 7/25/2024

**Inspector Signature:**

**Client Signature:**